piece on three strips instead of on a continuous surface in order i to facilitate assembling. When this is necessary, it is advisable to make the strips in such a way that they can be readily J replaced when worn. The supporting points should be so located that they be easily reached for cleaning, in order that locations will not be affected by an accumulation of chips or dirt at important ( Adjustable points should be so arranged that dirt points. and chips will not clog the screws and thus make them difficult to This point in design should receive careful operate. attention when fixtures are designed for use on the vertical turret

lathe

or vertical boring mill On machines of the horizontal type,

less trouble is likely to be experienced in this respect, because

the chips do not tend to fall on the screws. In either case.

however, it is always well to provide against any trouble this source.

It is frequently desirable to insert hardened steel buttons uniform height in the jaw screw holes in order to raise a portion of the work above the tops of the standard jaws, so that the work can be faced or under-cut. These buttons form an excellent three-point support for the work in addition to performing the function already mentioned. Short parallels cut from coldrolled steel may be used on a vertical turret lathe and are somewhat cheaper than the buttons, but they are open to the objection of becoming easily displaced and lost. When it is necessary to arrange points to act as a vee on cylindrical surfaces, it is good practice to make them so that they can be adjusted to take up wear. This can easily be by means of headless set-screws with check-nuts to lock them securely in any position; and it is a better construction place one check-nut on the outside and another one inside. than to have both nuts on one side of the fixture wall Ι construction of the fixture will not always permit of using f method, but, when it will, very satisfactory results are obtained. ) When the three-point support is applied to the fixture itself, the clamp screws which hold the fixture in place on the table should be arranged at the points where the supports are placed,